



NOTES:

1. OVERLAP SECTIONS 4" AND SEAL SEAM WITH 3" QUICKSET TAPE
2. SEAL ENDS OF BARRIER TO ADJOINING STRUCTURE
3. CUT OPENINGS NEAT AND CLEAN AT ALL PENETRATIONS OF BARRIER. OVERLAP INSUL-QUILTS PLENUM AND SEAL "AIRTIGHT."